


SPRING CONTACT TEST SET UP

Alec Webster
9/26/00

- glue 2 separate detectors, one w scotch weld 1838, one with white silicone adhesive
- mount in same manner as ladder thermal test to prevent 'potato chipping'
- measure resistance of contacts with UCSC resistivity set-up


TOP VIEW



trace break

spring contact

150 u glue



SIDE VIEW