

SCIPP SANTA CRUZ, CA 95064 408-459-2694	PAGE SIZE: B
BABAR HDI LINK CARD HDI SIDE I/O BLOCK	
SLAC DRAWING NO. SD350-700-15-C03 REVISION: 3 6/10/98	FILENAME: HDI_IO1.SCH PAGE 1 OF 1